



## SignalLink™ USB - RF Interference Fix

It has been reported when using the Tigertronics SignalLink™ USB unit in a very high RF environment, some RF may work its way into the SignalLink™.

The easy fix is to install one DX Engineering **DXE-CSB-750P** Ferrite Bead on the cable (four loops of cable through the Ferrite Bead) running from your radio to the SignalLink™ USB radio input. The addition of this ferrite bead cured the reported problem.



July 2008 - Problem Reported: Icom 756 Pro III, RTTY, 1.5 kW power. Your results may vary.

© DX Engineering 2008  
P.O. Box 1491 · Akron, OH 44309-1491  
Phone: (800) 777-0703 · Tech Support and International: (330) 572-3200  
Fax: (330) 572-3279 · E-mail: [DXEngineering@DXEngineering.com](mailto:DXEngineering@DXEngineering.com)